

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರವರ ಕಛೇರಿ,  
ನಂ.4 ಕಟ್ಟಡಗಳ ಉಪವಿಭಾಗ  
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಬೆಂಗಳೂರು-560 001.



ದೂರವಾಣಿ ಸಂಖ್ಯೆ: 080-22267585  
ಇ-ಮೇಲ್: aeeno4bldg@gmail.com

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಂ: ಸಕಾ/ಕಲವಿ-4/ಸ.ಇಂ/ಕ.ದೃಢೀಕರಣ ಪತ್ರ/2023-24/1188

ದಿನಾಂಕ: 9/1/2024

To,

Principal,  
Daffodils Foundation for learning,  
16<sup>th</sup> Main Road ,A.E.C.S Layout,  
Sanjayanagara,  
Bangalore -560094.

Sri,

Subject: Regarding issue of Stability certificate for school building

Ref: 1. Your Stability certificate request letter dated: 01.01.2023

2. Circular letter from Additional Secretary, Public Works Department, Government of  
Karnataka. No: PWD 59 BED 2019 Bangalore Dated: 06.05.2022.

<<<<<<>>>>>>

In reference to the above subject, the school run by DAFFODILS ENGLISH SCHOOL ASSOCIATION (DESA) "Daffodils Foundation for learning" 16<sup>th</sup> Main Road, A.E.C.S Layout, Sanjayanagara, Bangalore -560094, vide the letter referenced in reference (1)—that the school building be granted a safety certificate.

As a result, the building of DAFFODILS FOUNDATION FOR LEARNING interior and exterior were jointly inspected by PWD Engineers and Smt. Madhuri Changappa, Secretary, DESA on 05.01.2024. The building comprises a basement, a ground floor, and three floors, with the third floor being constructed with light roofing that was built in 2013. The school has thirty-two classrooms and fifteen other rooms in addition to restrooms. The building's flooring is made of granite, ceramic, and cement, its windows are made of steel and aluminum, and its doors are made of wood.

Due to the lack of details regarding the materials used in the construction work, such as concrete grade, steel, cement, sand, etc. related to the building, two types of Non-Destructive tests has been conducted as indicated in the government circular cited in reference (2) and have been submitted to this office.

Further, Ultrasonic Pulse Velocity Test and Rebound Hammer Test were performed by U.V.C.E. Professor Dr. N. Jayaramappa, B.E (Civil), ME(Str), Ph.D. After that, he certified that "The building is safe and sound, and building is advisable for any tenancy and occupancy" and issued a Form for certificate for Structural Design Sufficient Report (Annex – C Clause 12.2.8).

Further You have submitted the following necessary documents.

1. Sanction Plan
2. Certificate for structural design sufficiency (Annexe –C)
3. Ultrasonic Pulse Velocity Test Report
4. Rebound Hammer Test result.

For an urban school or college as specified in Order No. (1) of the Government circular of reference (1) – Rs. 5,000.00 as fee has been paid by you via Challan Reference No: CR0124005900056294 dtd. on 04.01.2024.

All the floors of the school building and important places were checked and in one place there is dampness on the wall because there is stagnation of water on the chajja from outside, the same has to be attended at the earliest.

This certificate is subject to revocation at any time, and it will be automatically canceled if the building undergoes any future changes or additions. This certificate is not valid in case of any kind of natural calamity like earthquake, cyclone and man made disaster. As a result, the **Daffodils Foundation for Learning** school building, located at 16th Main Road, A.E.C.S Layout, Sanjaynagara, Bangalore – 560 094, has been granted the aforementioned stability certificate, allowing it to be used exclusively for educational purposes, and the building/ premises is fit for occupancy up to class XII.

Your faithfully,

  
Assistant Executive Engineer,  
No.4 Buildings Subdivision, Bangalore.  
No 4, ಕಟ್ಟಡ ಉಪ-ವಿಭಾಗ  
ಬೆಂಗಳೂರು -560001



**Dr. Sujatha Girish**  
PRINCIPAL

DAFFODILS FOUNDATION FOR LEARNING  
(Aff. No. 830870 School Code: 45806)  
16th Cross, AECS Layout, Sanjaynagar,  
Bengaluru-560094, Karnataka.  
E-Mail: dflprincipal@daffodils.education  
Mobile No.: +91 9449788470